

Okuma Spindle drive modules VACIII, VACIV and MIP Repair – Exchange – Sale

[Home](#) / [Service](#) / [Okuma](#) / [Spindle drive modules VACIII, VACIV and MIP of all sizes](#)



Okuma spindle drive
modules VACIII, VACIV and
MIP
Repair - Exchange - Sale



Drive module
repair



✓ In which quality/level
are load tests
performed at your
company?

Do you have special
spare parts, which are



✓ Can you parameterize the devices?

What processes are
✓ involved in the repair of drive modules?



Further
information

What are the example
✓ type designations for this device series?

Will I get a detailed
✓ repair report after a successful repair?



Can it happen that after
✓ repair my device
continues to show
errors?

✓ What does serial repair
or overhaul mean



Cost & Warranty

What are the costs for
repair or overhaul?
✓ What does "flat repair
rate or standard repair
price" mean?

✓ Is there a warranty for
the respective repair?



D6 VACIII Drive
Unit

4500.00 €

Buy



D22 or 1006-1232
VACIII-Drive Unit

7700.00 €

Buy



D11 or 1006-1222
VACIII-Drive Unit

5045.00 €

+49 6251 9888430

info@industry-part.com

www.industry-part.com

Buy



+49 6251 9888430

CONTACT

info@industryart.com www.industryart.com

industryart GmbH
Robert-Bosch-Straße 33 a
64625 Bensheim, Germany

Tel. +49 6251 98884 30

Fax +49 6251 98884 31

info@industryart.com

www.industryart.com



We are solution-oriented